Release Notes All products v10.3

Table of Contents

NEW FEATURES **2**

SUPPORT FOR AUTOCAD 2010 FORMAT ..... **ERROR! BOOKMARK NOT DEFINED.**
DFM SLIVER CHECK ..... **ERROR! BOOKMARK NOT DEFINED.**
DFM VOID DETECTION AND FIXING ..... **ERROR! BOOKMARK NOT DEFINED.**
GENERATE MICROCRAFT .EMM FILES ..... **ERROR! BOOKMARK NOT DEFINED.**
BETTER MEMORY MANAGEMENT 2

ITEMS FIXED SINCE V10.2.2 ..... **3**

New Features

Better Memory management

GraphiCode has updated the internal tools used to manage memory allocation and usage.

Items fixed since v18.2.2

This list is customer reported issues fixed for this release.

#4463 Fixed a bug in the layer reduction algorithm caused by a poor polygon construction that resulted in an incorrectly drawn gerber layer.
#4460 Applied a consistent polygon interaction methodology for Gerber files and DPF files to correctly display a polygon interaction that was previously causing a cutout.
#4455 Fixed an issue caused by precision level in the DPF translator that caused very, very small arc segments to be interpreted as single points rather than full circle arcs.
#4454 Updated the Import wizard to accept Rounded Rectangle apertures for all layers rather than on a layer by layer basis. This will speed up import of multiple RS-274X layers with custom apertures describing Rounded Rectangles.